


Ejemplo de diagramas de control para el problema de la práctica 8:

X-BAR Mean: 74,0013 (74,0013) Sigma: ,009620 (,009620) n: 5



Range Mean: ,022375 (,022375) Sigma: ,008312 (,008312) n: 5

